



MUNICIPAL CORPORATION OF DELHI
OFFICE OF THE ASSISTANT ENGINEER
MAINTENACE-I, NARELA ZONE
ZONAL OFFICE, NARELA, DELHI-110040

No. AE(M-I)/MCD/2024-25/ 101

DATED: 18.08.2025

BUILDING FITNESS CERTIFICATE

Reference to the application vide NULL dated 12.08.2025 regarding issuance of Building Fitness Certificate of the existing building Mother Khazani Convent School, Mungeshpur, North District, Delhi-110039 comprised of Ground Floor and First Floor owned/occupied by Mother Khazani Convent School.

As per the documents/undertakings submitted with the application, Mother Khazani Convent School, Mungeshpur, Delhi-110039 building/premises complied with the Building Safety requirements in accordance with National Building Code Rules. A visual inspection of the building by the officer concerned of Municipal Corporation of Delhi in the presence of Principal/Head of the School was conducted on 13.08.2025.

Accordingly, it is herein verified that the building/premises is apparently safe/fit for normal use as a school building for a period of 01 year with effect from date of issuance of the certificate, in accordance with rules and subject to compliance of the specific conditions as mentioned hereunder.

This certificate is issued on 18.08.2025 at Narela, Delhi.

Cypd 18-8-25
Assistant Engineer (M-JNZ)
Asstt. Engrs (Works)
MCD
Narela Zone, Delhi-40

✓ The Principal
Mother Khazani Convent School
Mungeshpur, Delhi-110039

Conditions:

- The building can be safely occupied/used for running of the school purpose only.
- The certificate is issued only on the basis of visual inspection by the M.C.D. Engineer, considering the documents/undertakings submitted by H.O.S. be true and authentic.
- The certificate has no concern to any un-authorized construction in the premises and land dispute titles and other such issues.
- In case any addition/alteration or expansion and modifications to the building is to be carried out, the same shall be carried out under the supervision of a qualified Engineer and this certificate shall be reobtained after completion of the same.
- In case the building is affected by flood, or if there is settlement of walls/foundations or sagging of roofs etc. immediate inspection of qualified Structural Engineer be arranged to check the stability and safety of the building and this certificate shall be reobtained.